



To: U.S. and Canada Distributors
Dealer Principals
Service Managers
Warranty Managers
Parts Managers

Bulletin: SRA-V15-05
Date: October 9, 2015
Action Required? **YES**

From: Regulatory Affairs Department

Subject: Safety Recall, RVXX1505, OSRAM Sylvania Sealed Beam

Summary:

Description of Defect:

According to OSRAM, "The subject headlamps may not meet the minimum intensity requirements at certain test points as specified in CMVSS No. 108, S10.13.3 and Tables XVIII and XIX-b."

Also according to OSRAM, "These headlamps may not provide sufficient illumination of distant objects or the roadway. Insufficient illumination could result in a vehicle crash."

Volvo has not received reports of vehicle crashes.

Models/ Model Years Affected:

Volvo: Certain 2015 and 2016 VAH and VHD model vehicles manufactured from April 2, 2014 through August 14, 2015 with a OSRAM Sylvania Type 1C1 (H5001) and 2C1 (H5006) sealed beam headlamp.

Vehicle Quantities:

Volvo: 1,820 in total (1,669 U.S., 151 Canada).

Dealer's Responsibility:

The National Traffic and Motor Vehicle Safety Act and Canadian Motor Vehicle Safety Act requires dealers to ensure that all new and used vehicles are free of safety defects and comply with all relevant safety standards at the time of delivery to the consumer.

Dealers should make their personnel aware of the safety recall. In the event that a dealer has a vehicle included in the safety recall in their inventory to be sold, the condition must be corrected before releasing it to a customer.

Release Schedule:

- Vehicle will be posted on the Trucks Dealer Portal October 9, 2015.
- Repair Instructions are tentatively scheduled for release no later than December 3, 2015.
- Owner Notices are scheduled to be mailed on or before December 3, 2015.

Questions:

Contact the Regulatory Affairs Department at vtna.regulatoryaffairs@volvo.com if you have questions.