



Recall Alerts

To: Dealer Principals
Service Managers
Warranty Managers
Parts Managers

Region: U.S.
 CAN

Bulletin: SRA-V21-03
Date: October 19, 2021
Valid to: N/A

Action Required? Yes No

From: Gerard Hones, Regulatory Specialist Government Reporting
Subject: Safety Recall RVXX2103, DRL Non-Compliance

Description of Defect:

Volvo has determined that on certain model year 2022 vehicles the tail lamps do not turn on when the daytime running lamps (DRLs) are on. New Canadian regulations require that if a vehicle has dash backlighting, the low beam headlamps and tail lamps must automatically switch on when it is dark or the tail lamps must stay on at all times. Driving without tail lamps in low light conditions could make the truck less visible and increase the risk of a crash.

To correct this the vehicle software will be updated at a Volvo Parts and Service Center.

Models/ Model Years Affected:

Certain 2022 Volvo VAH, VHD, VNL, and VNR model vehicles manufactured from September 1, 2021 through October 4, 2021.

Vehicle Quantities:

Volvo 190 (all Canada)

Dealer's Responsibility:

The National Traffic and Motor Vehicle Safety Act and Canadian Motor Vehicle Safety Act requires dealers to ensure that all new and used vehicles are free of safety defects and comply with all relevant safety standards at the time of delivery to the consumer.

Dealers should make their personnel aware of the safety recall. In the event that a dealer has a vehicle included in the safety recall in their inventory to be sold, the condition must be corrected before releasing it to a customer.

Release Schedule:

- Vehicle list will be posted on the Trucks Dealer Portal October 19, 2021.
- Owner notification letters will be released on or before November 24, 2021.

If you have questions or concerns about this recall, contact the Regulatory Affairs Department at vtna.regulatoryaffairs@volvo.com.