

Safety recall #: **RVXX1403**

Title: Disc Brake Caliper Bolts

Summary: *The bolts that hold the disc brake caliper to the backing plate may have not been tightened to specification; therefore, the disc brake caliper may come detached from the backing plate. If this occurs, the brakes at that particular wheel will be affected, which may result in the vehicle “pulling” to the left or right when the brakes are applied.*

Volvo has not received reports of vehicle crashes and considers this as a proactive measure to protect the public and our customers.

*The recall involves approximately **4,081 in total (3,175 U.S., 635 Canada, 271 Mexico)***

Affected Models: Volvo VAH, VNL and VNM, 2014-2015

Questions: please contact the Regulatory Affairs Department at vtna.regulatoryaffairs@volvo.com.

Documents: