Safety recall #: RVXX1404

Title: D16 Programming

Summary: The engine control unit may have an incorrect parameter setting in the software, which may cause the engine to stall. If the engine stalls, the power steering and other safety related devices can become inoperable which increases the risk of a vehicle crash.

Volvo has not received reports of vehicle crashes and considers this as a proactive measure to protect the public and our customers.

The recall involves approximately 217 in total (46 U.S., 171 Canada)

Affected Models: 2015 Volvo VNL and VNX model vehicles with a D16 engine from November 6, 2013 through June 24, 2014.

Questions: please contact the Regulatory Affairs Department at <u>vtna.regulatoryaffairs@volvo.com</u>.

Documents: