

Volvo Trucks

Uptime



Recall Alerts

To: U.S. and Canada Distributors
Dealer Principals
Service Managers
Warranty Managers
Parts Managers

Region: U.S.
 CAN

Bulletin: SRA-V18-03
Date: November 28, 2018
Action Required? Yes No

From: Name, Title

Subject: RVXX1803, Bridgestone Americas Tire Operations, LLC Recall

Description of Defect:

On, certain trucks manufactured in North America from May 21, 2018 through October 3, 2018 equipped with Bridgestone M864, M860A or M854 wide-base tires, size 425/65R22.5, may not conform to the endurance testing requirements of Motor Vehicle Safety Standard 119 - Tires for vehicles other than passenger cars. This issue could cause a bulge or blister in the sidewall of the tires, which over time could cause deterioration of the tire's structure.

Models/ Model Years Affected:

Volvo: Certain 2019 VHD and VNL

Vehicle Quantities:

Volvo: Approximately 122 vehicles (103 U.S., 19 Canada)

Dealer's Responsibility:

The National Traffic and Motor Vehicle Safety Act and Canadian Motor Vehicle Safety Act requires dealers to ensure that all new and used vehicles are free of safety defects and comply with all relevant safety standards at the time of delivery to the consumer.

Dealers should make their personnel aware of the safety recall. In the event that a dealer has a vehicle included in the safety recall in their inventory to be sold, the condition must be corrected before releasing it to a customer.

Release Schedule:

- Vehicle list will be posted on the Trucks Dealer Portal November 28, 2018.
- Owner notification letters will be released on or before December 21, 2018

If you have questions or concerns about this recall, contact the Regulatory Affairs Department at vtna.regulatoryaffairs@volvo.com.